PPE Requirements

Course	PPE Requirements
Substation Entry	ARC Rated clothing, Nitrile gloves, Safety glasses, Hard hat, Safety boots
Disconnect/Reconnect	ARC Rated clothing, Nitrile gloves, Safety glasses, Hard hat, Face shield, LV Working gloves, Safety
M1809 NS146 Pre work Pole Inspection	ARC Rated clothing, Manual handling gloves, Safety glasses, Hard hat, Safety boots
TTDO1570 Insulate LV mains	ARC Rated clothing, Manual handling gloves, Safety glasses, Hard hat, Safety boots, LV gloves and outers, Harness and Lanyard, test lamps, EWP if required.
TTDO1653 LV Shorts	ARC Rated clothing, Manual handling gloves, Safety glasses, Hard hat, Safety boots, LV gloves and outers, Harness and Lanyard, test lamps, EWP if required.
TTDO1804 HV Earths up to 132KV	ARC Rated clothing, Manual handling gloves, Safety glasses, Hard hat, Safety boots, LV gloves and outers, Harness and Lanyard, test lamps, EWP if required.
TTDO1400 Streetlighting service worker	ARC Rated clothing, Manual handling gloves, Safety glasses, Hard hat, Safety boots, LV gloves and outers, Harness and Lanyard, test lamps, EWP if required.